
Approved For Release 2009/07/24: CIA-RDP80T00246A001900500001-5



Approved For Release 2009/07/24: CIA-RDP80T00246A001900500001-5

Approved For Release 2009/07/24 : CIA-RDP80	T002464001900500001-5
	This material contains information affecting the
INFORMATION REPORT	National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C.
PREPARED AND DISSEMINATED BY	Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized per-
CENTRAL INTELLIGENCE AGENCY	son is prohibited by law.
COUNTRY Hungary	
SUBJECT	DATE DISTRIBUTED
Hickory in Pastern Homeson Million to a con	12 September 1957
Highways in Bastern Hungary Maintenance plans and methods Sketches of Cross-Sections of various highways	NO. OF PAGES NO. OF ENCLS.
Class coation - Combined by	SUPPLEMENT TO REPORT #
coss sections of various regressers	1
THIS IS UNEVALUATED INFORMA	TION
	<del> </del>
2. The specific plans or actual road construction at Kecskemet are as follows:	t Szeny, Bekescsaba, and at
a. Szony [47 44 N / 18 10 E]	
· · · · · · · · · · · · · · · · · · ·	
(1) Highway No 1, the primary route between Bus class highway and when last observed (mid- It is slightly more than six meters in width there is a one and one-half degree grade for the sub-grade of the road itself is composed case where the ancient Roman road has been end. The lower course has a 25 cm depth of and rock varying in size from 10 cm to 15 of course, the surface, has a five cm depth of incapable of supporting vehicles during incompanies ditches are adequate for all periods they have a depth of 50 cm to 120 cm, with four and one-half meters and also a flat be track railroad on an eight meter roadbed particles.	1956) was in excellent condition. th with two meter width shoulders. From the center crown of the road. The condition of compacted earth, or in the utilized, of wooden blocks on the bituminous macadam (gravel cm in diameter). The upper of asphalt. The shoulders were cleanent weather. The existing cleanent weather. The existing cleanent weather in the existing cleanent weather. The existing cleanent weather than the condition of the condition
(2) Other highways emanating from the city of S the plans for a new "utili run between an oil refinery, Szony Olajipar meters east of the town and the Danube Rive 300 meters, three meters in width with two road is programmed for completion sometime utilized primarily for repair trucks and mo	ity" macadam road which will ri Vallalat, located two kilo- er. Total length is to be meter width shoulders. This in 1957. This road will be
b. Bekescsaba [46 39 N / 21 05 E]	

25X1

25X1

25X1

Approved For Release 2009/07/24 : CIA-RDP80T00246A001900500001-5

DISTRIBUTION

July 1956. The surface of this particular road was composed of a top layer of concrete 18 cm in depth.

- (2) The method employed by the road maintenance crews on this and comparable highways in the area is as follows: Cracks in the concrete are blown clean by compressed air hoses and then filled with asphalt. When a depressed area is noted, as a result of a compacted sub-surface or possibly by heavy vehicular traffic, the maintenance crews drill a hole in the depression and shoot cement (gunite) into the depressed area, until the surface is flush once again.
- (3) The main roads leading away from Bekescaaba to the west are in relatively good condition. Highways 40-23 and 437 passed over a railroad (Orient-Express) approximately one and one-half kilometers west of the city. This track is a single line only, however the highway overpass has been lengthened for possible laying of an additional parallel track.

## c. <u>Kecskemet</u> [46 54 N / 19 41 E]

- (1) Highway No 523 running south from Macskemet to Kiskunfelegybaza [46 43 N/ 19 51 E] and Baja [46 10 N / 18 56 E] was initially planned to be a first-class route, but after only 20 kilometers was straightened and improved (1953) the program was dropped. This was due to the increased tension developing between Tito and Stalin.
- (2) all of the secondary roads in this particular area have been greatly improved Increased emphasis was given to changing the third-class roads into all-weather routes. The small villages appeared to be more willing to do their share in cooperating with the national roadbuilding program.
- (3) In this particular area, the first conscientious effort to increase the turn radius of the highways was made. Prior to WWII, numerous roads had turn radii of less than 300 meters. In the reconstruction program, a minimum turn radius was established at 500 meters. The only exception to this is in the case of a highway paralleling a railroad and then crossing it.
- Practically all the plans formulated have been fulfilled with the exception of Highway No 523 [see paragraph 2c(1) above) near the Yugoslavia border.

# the best all-weather highways in eastern Hungary are as follows:

#### a. First Class

- (1) Highway No 5 (Budapest-Kecskemet-Szeged). Last observed in July 1956.
- (2) Highway No 4 (Budapest-Cegled-Szolnok-Debrecen-Nyiregyhaza. Last observed in 1954. this road could have been greatly torn up due to heavy tank traffic at the time of the October 1956 revolution.
- (3) Highway No 3 (Budapest-Hatvan-Miskole). Last observed in 1954.

#### b. Second Class

- (1) Highway No 40 (Kecskemet-Bekescsaba). Last observed in July 1956.
- (2) Highway No 43 (Oroshaza-Bekescsaba). Last observed in 1954
- (3) Highway No 52 (Kecskemet-Cegled). Last observed in 1954.

### c. Third Class

(1) Highway No 435 (Bekescsaba-Gyula). Last observed in 1955.

C-O-N-F-I-D-E-N-T-I-A-L

25X1

25X1

	• 3 =	25X
4.	the drainage system beneath the roads (culverts) was adequate. These culverts, for the most part, were composed of concrete poured at the site by utilizing steel or wood forms. Pre-cast concrete sections were also used extensively. Minimum depth of the culverts below the surface of the road was 50 cm. They were standardized as to size and were 60 cm, 80 cm, and 120 cm in diameter. Approximately 50 percent of the pre-cast culverts were elliptical in shape for greater load-bearing capability.	25X
5۰	the rerouting of Highway No 21 between Jobbagyi [47 50 N / 19 41 K] and Passto [47 55 N / 19 42 K]. This rerouting was of possible significance as the direct route between the two towns was in fair condition at the time, and the change necessitated utilization of two bridges	25X
	across the Zagyva River. The total distance for this diversion was nine kilometers.  the construction of this obviously duplicated road.  a projected classified area to be located approximately one kilometer north and one kilometer east of Jobbagyi.	25X
		25 <b>X</b> 1


......


C-O-N-F-T-D-E-N-T-T-A-L


								25
io	1 -	Reprod	uced fro	m Magyaro	rszagi	Av	toutak Terkepe 1956 Budapest	
		(Highw	ays 1, 8	08,80,8	1) (8	ZO	ny)	
0	2 -		sketch	- Cross S	ection	of	Budapest-Wein Highway	25
o	3 -	11	Ít	11	11	n	Szekesfehervar-kisber and Kisber- Komarom Highways	
o	4 -	n	11	ti	11	**	Highway 80	
o	5 <b>-</b>	H	n	11	11	11	A, B, C Utak Highways	
0	6 -						toutak Terkepe 1956 Budapest kescsaba)	
To	7 -		sketch	- Cross S	ection	of	Kecskemet-Bekescsaba	2
<b>To</b>	8 -	11	#1	11	is	**	Debrecen-Szeged Highway	
ĬΟ	9 -	11	<b>\$7</b>	11	11	Ħ	Debrecen-Szeged Highway	
NO.	10-	E	67	11	17	97	Bekescsaba-Gyula Highway	
No	11-	11	ţţ	17	u	11	Bekescsaba-Mako Highway	
No	12-	11	11	tı	*1	38	B,C,D,E,F - Utak Highway	
No	13-		roductio cskemet)	n from Ma	gyarori	3 <b>2.6</b> .	gi Autotak Terkepe 1956 Budapest	
No	14-		Sketch	- Cross S	ection	of	Budapest-Szeged-Orszaghatar Highway	25
No	15-	11	11	27	11	11	Cegled-Kecskemet Highway	
No	16-	11	11	11	17	tt	Kecskemet-Dunafoldvar Highway	
No	17-	11	***	n	51	71	Kecskemet Highway	
No	18-	ti	tt	tī	11	n	A,B,C,D,E, Utak Highways	
No	19-	31	11	n	FT	11	Paszto [4755N/1942E] to Jobbagyi [4750N/1941E] "By-pass"	


CONFIDENTIAL


a-proc.











Approved For Release 2009/07/24 : CIA-RDP80T00246A001900500001-5

